

INTENDED USE

To insulate between different materials in order to reduce or prevent contact between dissimilar metals which can lead to galvanic corrosion.



INSTRUCTION FOR USE

Ensure the surface is clean, dry and free from oil or other contaminants. Remove the backing paper and fix the tape, pressing evenly and firmly to remove any air pockets. Gentle heat may be used to form around tight angles.

When fixing clamps or brackets, ensure there are no sharp edges or points which may penetrate the insulation tape. When tightening, ensure the tape does not become compressed to failure. Check there is no conductivity between the parts.

The insulation material may creep under compression and temperature over time, critical fasteners should be included in routine checks to ensure they remain sufficiently tight.

Available in 20 and 50 mm widths.



User Guide for Bolts:
Recommended Torque