

0-1km

Hilti Corrosion handbook / DFTM

2

SF BT 22-A
SF BT 18-A

7a

DX 351 BT

11b

Min. ✓ Min. ✗

X-BT: 25.7 mm

$\leq 0,5 \text{ mm} / 0,02''$
 $\geq 8 \text{ mm} / 0,32''$
 $\leq 0,5 \text{ mm} / 0,02''$

3

4

7b

8

X-BT-MR

12

2-14 mm
5/64" - 35/64"

13-14 mm
1/2" - 9/16"

		Use with		
	✓			
X-BT-MR M8/14 SN 8	✓	TX-BT 4.7/7 80	DX 351-BT	S-NS 13C 95/3 3/4"

5

9

$\leq 200 \text{ N}$

10

13A

X-BT 1/4"
20 Nm / 14.8 lb-ft

1 ↓
2 ↻
3 click! ↓ STOP

13B

SF 14-A	3	12
SF 10W	4	8
SF 8M-A22	4	12
SFC 14-A	2	13
SFC 22-A	2	14
SF 6-A22	1!	1!

$\leq 5 \text{ N}$

13C

$\leq 20 \text{ Nm}$
14.8 lb-ft

T_{inst}

1

6



$\phi 4,7 \text{ mm}$
6,7 mm

11a













Max. ✓ Max. ✗

X-BT: 26.8 mm

14



		Use with		
X-BT-MR M8/14 SN 8	TX-BT 4.7/7 80	BX 3-BT	X-BT 1/4" - 20Nm/ 14,8 ft lb	S-NS 13C 95/3 3/4"



14A

X-BT 1/4" 20Nm / 14.8 lb-ft

1 ↓
2 ↻
3 click! ↓ STOP

14B

SF 14-A	3	12
SF 10W	4	8
SF 8M-A22	4	12
SFC 14-A	2	13
SFC 22-A	2	14
SF 6-A22	1!	1!

≤ 5 N

14C

≤ 20 Nm
14.8 lb-ft

T_{inst}

