


















S-BT-MR M6/15 SN 6
S-BT-MR W6/15 SN 6
S-BT-MR M8/15 SN 6
S-BT-MR M10/15 SN 6
S-BT-MR W10/15 SN 6


Hex nut with flange M6-A4
Hex nut with flange W6-A4
Hex nut with flange M8-A4
Hex nut with flange M10-A4
Hex nut with flange W10-A4

	SBT 4-A22 SF BT 18/22-A
	TS-BT 5.5-74 S
	SBT 4-A22 SFC 18/22-A
	S-DG BT M6 - W6 / 15 Long 6 S-DG BT M8 / 15 Long 6 S-DG BT M10 - W10 / 15 Long 6
	S-CC BT 6

Torque tool X-BT 1/4"
8 Nm / 5.9 ft.lb

S-NS 10 C 95/3 3/4" (M6)
S-NS 5/16" C 95/3 3/4" (W6)
S-NS 13 C 95/3 3/4" (M8)
S-NS 15 C 95/3 3/4" (M10)
S-NS 9/16" C 95/3 3/4" (W10)





S-BT-MR M6/15 SN 6
S-BT-MR W6/15 SN 6
S-BT-MR M8/15 SN 6
S-BT-MR M10/15 SN 6
S-BT-MR W10/15 SN 6

Hex nut with flange M6-A4
Hex nut with flange W6-A4
Hex nut with flange M8-A4
Hex nut with flange M10-A4
Hex nut with flange W10-A4

	SBT 4-A22
	TS-BT 5.5-74 S
	SBT 4-A22 SFC 18/22-A
	S-DG BT M6 - W6 / 15 Long 6 S-DG BT M8 / 15 Long 6 S-DG BT M10 - W10 / 15 Long 6
	S-CC BT 6

Torque tool X-BT 1/4"
8 Nm / 5.9 ft.lb

S-NS 10 C 95/3 3/4" (M6)
S-NS 5/16" C 95/3 3/4" (W6)
S-NS 13 C 95/3 3/4" (M8)
S-NS 15 C 95/3 3/4" (M10)
S-NS 9/16" C 95/3 3/4" (W10)

